

IPX7 TEST REPORT

Applicant Company : **WenZhou Welland Electric Co., Ltd**

Address : **1168, DaoHang Road, RuiAn Economic DVPT Zone,
WenZhou, ZheJiang, China**

Manufacturer Company : **Same as applicant**

Address : **Same as applicant**

Sample Name : **Water Flosser**

Model Number : **WL2117,WL2117P**


Date of Report : **Jun. 27, 2022**

Date of Tested : **Jun. 24, 2022**

TESTING LABORATORY : **Shenzhen Most Technology Service Co., Ltd.**

NAME : **Shenzhen Most Technology Service Co., Ltd.**

ADDRESS..... : **No.5, 2nd Langshan Road, North District,
Hi-Tech Industrial park, Nanshan, Shenzhen,
Guangdong, China**

	Name	Signature	Date
Testing Engineer	Qinghua Hu		June 30, 2022
Approving Manager	Jack Cheng		June 30, 2022

Notes:

1. This report will be invalid if duplicated or photocopied in part.
2. This report refers only to the specimen(s) submitted to test, and is invalid as separately used.
3. This report is invalid without examination stamp and signature of this company.
4. The tested specimen(s) will be preserved for thirty days from the date issued, if not taken back by the applicant.

1: Test item

IPX7 test

2: Test environment

Temperature: 23.6°C

Relative humidity: 65%RH

3: Test sample description

The test samples come from the customer. They are Water Flossers. All models are the same except the model name.

4: Testing standard

IEC 60529:1989+A1:1999+A2:2013 Degrees of Protection provided by enclosures (IP code).

5: Test requirement and result

IPX7 test

Test requirement: In general, after complete tests, specimen operates normally and no feed water, or if have water, should not affect the normal operation of the equipment or safety.

Test result: There is no water inside, not affect the creepage distance and normally operation, the test is pass.

6: Test instrument used

Item	Test instrument	Model No.	Manufacturer	Serial No.	Last Cal.
1	IPX1-X7 water-proof tester	JPY1351	Jinpuyang	1909325752	2022.3.24
2	Steel tap	/	Ruixiang	/	2021.12.9
3	Withstand voltage tester	LK2678B	Blue Bright	W72D-0319-029	2022.5.12

Attachment: Photos of the appliances

Photo1

Description: Overview of WL2117



Photo2

Description: Overview of WL2117



Photo3

Description: Overview of WL2117




Photo4

Description: Overview of WL2117



Photo5

Description: Test Photo



Photo6

Description: Test Photo



Photo7

Description: After testing of IPX7 WL2117s



Photo8

Description: After testing of IPX7 WL2117





Photo9

Description: After testing of IPX7 WL2117



-- The End of Report--